

January 5, 2010 7:35:04 AM

Item ID:

DSI 9367-011

Accept



Setup Start

Stop



Revision ID:

Item Name: **Start Date:**

Wearshoe

1/05/10

Start Qty: 2.00

Reg'd Oty: 2.00



Cust Item ID:

Customer:

Reference:

Process Plan: Approvals:

Required Date: 1/08/10

Date:

Tooling:

0.00

Date:

Run Start

QC:

Date: SPC (Y/N):

Date:

Stop

Sequence ID/ Work Center ID

Operation Description Set Up/ **Run Hours**

Draw Number

Draw Rev.

Pian Accept Qty Code

Reject Qty

Reject Number

Insp. Stamp

Draw Nbr

Revision Nbr

DSI 9367 Rev A

100

Document Control

DOCUMENT CONTROL Memo

0.00

Photocopy bluefile & type labels per PPPDS19367-011

110

Packaging Packaging

Pick Kit

0.00

Memo

0.00

120

QC

0.00

Quality Control

Memo

QC4- 100% Inspect kits for completeness

Page 2

January 5, 2010 7:35:04 AM

Item ID:

DSI 9367-011

Accept



Setup Start

Stop



Revision ID:

Item Name: **Start Date:**

Wearshoe

1/05/10

Start Qty: 2.00

Req'd Qty: 2.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan: Date:

Memo

Tooling:

Date:

Start Run

QC:

Required Date: 1/08/10

Date:

SPC (Y/N):

0.00

0.00

Date:

Stop

Sequence ID/

Operation **Work Center ID** Description Set Up/ **Run Hours**

Draw Draw Rev. Number

Plan Code

Accept Oty

Reject Qty

Reject Number Stamp

130

Packaging

Packaging

Packaging

Identify and pack for shipping as per PPP Dsi9363-011[]Location:

140

QC21- Final Inspection - Work Order Release

0.00



QC Quality Control

Memo

0.00

10/01/1398 ME 10-1-12

•												
Picklist Print January 5, 2010 7:35:6	01 AM											Pag
Work Order ID: • 54989	_	····										
Parent Item: DSI 93	367-011						Ē.					
Parent Item Name: W	earshoe		1156	***************************************	··· ··· · · · · · · · · · · · · · · ·			s	tart Date: 1/05	/10	Required Date:	1/08/10
Comments:									Start Qty: 2.00		Required Qty:	2.00
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
AN3C4A +24		Purchased	No			120	Each	1,195.000	48.0000	1-121)	sf	
				<u>Wareho</u> <u>Loc</u>	ouse ation	<u>Loc</u>	<u>Oty</u>	Loc Code				
				Main W	arehouse							
				ST			1195		_			
					112314		13		_			
					112720 112724		12 3					
					112724		1					
					112991		2					
				,	113121		64		7	J (5)		
					113226		586 14		_	19		
					113422		500					
AN3C6A 412		Purchased	No			120	Each	828.0000	24.0000		-A (
BOLT									 1 	10-11	1 24 (9	14)

S BOLT BOLT

Warehouse	Loc Qty	Loc Code	
Location			
Main Warehouse			
ST	828		
111982	828		24

January 5, 2010 7:35:01 AM

Work Order ID: 54989

Parent Item:

Comments:

DSI 9367-011

Parent Item Name: Wearshoe



Start Date: 1/05/10

Required Date: 1/08/10

Start Oty: 2.00

Required Qty: 2.00

Component Item ID/	Replacement	Mfg/	Bin	Primary	Last	Route	Unit of	Qty on	Remaining	Qty	Date	Status
Item Name	Item ID	Purch	Item	Location	Location	Seq ID	Measure	Hand	Qty To Pick	Issued	Issued	
AN3C7A 46		Purchased	No			120	Each	541.0000	₹ _{6.0000} / <i>t</i>	· 	s)	

		Warehouse	<u>L</u>	oc Oty	Loc Code	
		Location				
		Main Warehouse				
		ST		541		
		105906		21		
		107376		252		
		113149		268	44	16
Purchased	No		120	Each	416.0000 88.0000	

AN960C10L 444

145/149C0332R

Q51

	120	Lacii	410.0000	M113288	10-1-11	. 4
Warehouse	Loc	e Oty	Loc Code			0
Location						
OFFSHORE						
FG		100				
103585		100				
Main Warehouse						
ST		316				
112116		156				
112612		160				

January 5, 2010 7:35:01 AM

Work Order ID: 54989

Parent Item:

DSI 9367-011

Parent Item Name:

Wearshoe

Comments:



Start Date: 1/05/10

Required Date: 1/08/10

Start Qty: 2.00

Required Qty: 2.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D3564-1		Manufactured	No	*- ·		120	Each	23.0000	2.0000	··		
										>-/-8	S	

72 Wearshoe

Warehouse	Loc Qty	Loc Code	
Location			
OFFSHORE			
FG	2		
33798	2		
Main Warehouse			
ST	21		
47531	1		
50270	1		-
51676	19		<u>0</u> `
	120 Fach	13,0000 2,0000	

+2 Wearshoe

Manufactured

10-1-8

Warehouse	Loc Oty	Loc Code	
Location			
OFFSHORE			
FG	2		
33764	2		
Main Warehouse			
FP/	10		
50113	10		<u> </u>
Main Warehouse			
ST	1		
46445	1		

Picklist Print

January 5, 2010 7:35:01 AM

Work Order ID: 54989

Parent Item:

DSI 9367-011

Parent Item Name: Wearshoe

Comments:

Start Date: 1/05/10

Required Date: 1/08/10

Page 4

Start Qty: 2.00

Required Qty: 2.00

	Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
_	D3564-5 , 4		Manufactured	No			120	Each	14.0000	2.0000	n-1-8	~ ()	<u>ـــ</u>
1	Wearchoe	••••								110001000	071-0	ye	

12 Wearshoe

Warehouse	Loc Oty	Loc Code	
Location			
OFFSHORE			
FG	2		
34806	2		
Main Warehouse			
FP19	10		
51925	1		
53805	9		<u></u>
Main Warehouse			
ST	2		
45824	1		
47433	1		

January 5, 2010 7:35:02 AM

Work Order ID: 54989

Parent Item:

Comments:

DSI 9367-011

Parent Item Name:

Wearshoe

Manufactured



Start Date: 1/05/10

Required Date: 1/08/10

Start Qty: 2.00

Required Qty: 2.00

Component Item ID/ Replaceme Item Name Item ID	nt Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D3566-1 1 2	Manufactured	No			120	Each	27.0000	4.0000	0-)-9	S	2



2 Gasket

Warehouse	<u>Lo</u>	c Qty	Loc Code		
Location					
Main Warehouse					
FP		22			
52512		3			
(54480		19			9
Main Warehouse					·
ST		5			
46349		1			
51218		1			
51259		3			
	120	Each	15.0000	2.0000	

10-1-8

Warehouse	Loc Oty	Loc Code	
Location			
Main Warehouse			
FP C	11		
53804	11		2
Main Warehouse			
ST	4		
36113	1		
46186	1		
47318	1		
51260	l		



DESIG	n РН	DRAWN BY	DART		SPACE U t hadlock, wa	SA, I	NC.
CHEC	(ED	APPROVED /	DRAWING NO.				REV. ▲
	#	-14	DSI 9367			SHEET	r 1 OF 3
DATE			TITLE				SCALE
07.0	2.09		STAINLESS	STEEL	WEARSHOE	KITS	NTS
Α		07.02.09	NEW ISSU	Ξ.			

REFERENCE ONLY



DART SERVICE INSTRUCTION

REF. FAA STC: SR01583SE REF. CANADIAN STC: SH05-37 ISSUE 1

For customers with D412-742-011/-013 float skidtubes at CHG 002 or earlier who would like to upgrade to stainless steel wearshoes the following kit can be obtained from Dart:

- QTY / -011	Part Number	Description
Х	DSI 9367-011	WEARSHOE KIT
1 1	D3564-1	WEARSHOE (REPLACES D3460-1)
7 2	D3566-1/	GASKET
<u>_1</u>	D3564-3 /	WEARSHOE (REPLACES D3460-3)
1	D3564-5	WEARSHOE (REPLACES D2577-5)
11	D3566-5 /	GASKET
1 4		
24	AN3C4A	BOLT
12	AN3C6A	BOLT
J 8	AN3C7A	BOLT
44	AN960C10L*	WASHER

For customers with D412-742-011/-013 float skidtubes at CHG 002 or earlier who would like to upgrade the fwd and aft sections of their float skidtubes, the following kits can be obtained from Dart:

QTY -013	Part Number	Description
Х	DSI 9367-013	WEARSHOE KIT
1	D3564-13	WEARSHOE
1	D3566-13	GASKET
1	D3537-1	WEARPAD
1	D3553-1	GASKET
1	D3537-7	WEARPAD
1	D3553-3	GASKET
10	NAS1330C3KB166	INSERT
4	NAS1330C3KB266	INSERT
10	AN3C4A	BOLT
4	AN3C5A	BOLT
14	AN960C10L	WASHER